IN THE SPECIFICATION

Please replace paragraph [0008] of the specification with the following amended paragraph, in which insertions are indicated by underline and deletions are indicated by strikethrough or double brackets.

In the present invention constructed as described above, the bush member has the outward dowels projecting radially outward from the outer periphery of the boss portion, and the gear member has the inward dowels projecting [[radally]] **radially** inward from the inner periphery thereof. At least one of the shapes and dimensions of the outward and inward dowels is asymmetric. Therefore, when an assembling method other than a normal method is used, the tip of some dowel comes into interference with related parts. The dowel cannot be satisfactorily received in its normal position. For this reason, it is possible to carry out the assembly in the right way. Thus, the degree of freedom in the layout of the internal combustion engine is improved without being restricted by gear specifications.